



Shaft Earthing Solutions

info@shaftearthing.com | www.shaftearthing.com

RDM SM2-X


Shaft Current & Voltage Monitor
for hazardous areas

CURRENT/VOLTAGE
DISPLAY

ALARM DISPLAY

REMOTE ALARMS

4-20mA SIGNALS



SHAFT EARTHING SOLUTIONS

BRUSH #1		BRUSH #2	
PEAK	0.46 A	PEAK	2.22 V
AVERAGE	0.36 A	AVERAGE	1.29 V
HI ALARM SET	0.60 A	HI ALARM SET	3.00 V

ALARM OFF

SETTING: 1 5 10 50 A V

SHAFT EARTHING SOLUTIONS

BRUSH #1		BRUSH #2	
PEAK	0.91 A	PEAK	2.22 V
AVERAGE	0.41 A	AVERAGE	1.28 V
HI ALARM SET	0.60 A	HI ALARM SET	3.00 V

ALARM ON

SETTING: 1 5 10 50 A V

STATUS & SETTINGS

ALARM INDICATION

Applications

Simple Shaft Current and Voltage Monitoring
for machines in hazardous areas

Shaft Earthing Solutions